

APPENDIX N ~ Non ACBM ~ Building Construction List

WKU adheres to a modified version of the *Asbestos Hazard Emergency Response Act* (AHERA), a provision of the 1986 *Toxic Substances Control Act* (TSCA), to manage *asbestos containing building material* (ACBM) in buildings owned or maintained by the University.

The following buildings have been determined to contain no ACBM and subsequently placed on the WKU Non-ACBM Building Construction List:

- ★ Adams-Whitaker Student Publications Center
- ★ Augenstein Alumni Center
- ★ Baseball Concessions Building
- **★** Baseball Clubhouse
- ★ Baseball/Softball Batting Facility
- ★ Center for Engineering and Biological Sciences
- ★ Chandler Chapel and Columbarium
- ★ Clinical Education Complex
- **★** Chill Water Plant
- ★ College High Hall
- **★** Diddle Arena (*interior only*)
- **★** Gary Ransdell Hall
- * Gatton Academy
- ★ Glasgow Extended Campus
- * Guthrie Clock Tower
- ★ Health Services Building
- * Hilltopper Hall
- ★ Honors College and International Center
- Horticultural Greenhouses
- ★ Houchens-Smith Stadium West
- ★ Intramural Sports Complex Building
- **★** Jody Richards Hall (MMTH)
- ★ Kentucky Street Apartments
- ★ Music Rehearsal Hall
- **★** Northeast Hall (interior only)
- ★ Ogden College Hall
- ★ Owensboro Extended Campus
- ★ Parking Structure # 2
- **★** Parking Structure #3
- ★ Parking and Transportation Services Building
- ★ Softball Complex Building
- * South Campus
- **★** Southwest Hall (*interior only*)
- ★ Snell Hall
- * Student Success Center (North end of DSU)
- **★** Tower Food Court
- * WKU's Center for Research and Development (interior only)

The following criterion qualifies a WKU building as free of ACBM and only applies if the structures were constructed or fully renovated after October 12, 1988:

Under the Asbestos Hazard Emergency Response Act, (AHERA) 40 CFR 763.85(a), as defined in 40 CFR 763.103; (1) an architect or project engineer responsible for the building construction, or an accredited asbestos inspector, signs a

statement that no ACBM was specified as a building material in any construction document for the building or (2) to the best of their knowledge, no ACBM was used as a building material in the building.

Rev. 6/13/23